

Building Report | Parking Lot Renovations | Lots 1 & 2

8.16.19

The following are pictures from the week of 8.12.19-8.16.19 in regards to Parking Lot Renovations Project. This is the first of only a few reports for this project. This year we are focusing on Parking Lots 1 and 2 to be renovated as they the two busiest parking lots on campus. Thus far the work completed in these lots has been both have had their existing asphalt pulverized and crushed, and both are being regraded to aid in proper drainage. Parking Lot 1 had additional drain tile added near its east end along with some existing concrete curbing being replaced. Parking Lot 2 required a few existing storm water structures to be extracted and repaired, and will receive additional structures to help solve some legacy drainage issues. Both lots will receive new asphalt pavement and striping in the next few weeks.



The top-left photo the circular drop off area at the end of the drive in front of the Health Education Building that is connected to Parking Lot 1. This area along with the adjacent lot will be re-paved.

The top-right photo shows one of two existing storm water structures from Lot 2 that has been pulled and will be repaired before being re-installed. The collar on this particular structure was collapsing.

Below is an overall map of Main Campus for reference in reading this report. Parking Lots 1 and 2 have been labeled.

