


Building Report | Millage Projects: Sidewalk Repairs

11.2.18

The following are pictures from the week of Oct. 8-12, 21018 in regards to this year's sidewalk repairs as part of our overall list of Millage Projects. This will be the one and only report on this project as all the work needed was accomplished in only one week thanks to some very favorable weather. This year we addressed 19 areas that were in need of attention including segments of walk that were either badly deteriorated, sunken, and/or lifted. Additionally, there was one drain collar adjacent to the CTC that required immediate attention, that was not only replaced, but upgraded for a better long-term solution. Sidewalk repairs are a yearly item that we address with an audit each spring as we are building the budget for the next fiscal year, and so this is a continuing effort we put forth to help ensure the health and safety of our students and staff as we strive to be good stewards our of wonderful campus and facilities.



The top-left photo shows 4 flags (or segments) of walk that had sunken and become hazardous that are now replaced and therefore safer for campus occupants and equipment to utilize.

The top-right photo is of the newly replaced drain collar near the CTC. This collar had failed and was a hazard for the delivery vehicles dropping off gas tanks to the welding lab storage area.

The map below shows the areas around Main Campus that were addressed with this year's sidewalk repairs.

